

The engraving results are poor

general rules:

- 1) Make sure you only use sharp cutters.
- 2) Make sure your cutters have been sharpened using the correct grinding angles for the material you have to engrave.
- 3) Always try not to engrave deeper than necessary. For plastics this means just deep enough to get through the top layer.
- 4) If you have to colour fill engravings, e.g. in aluminium, the engraving depth needs to be 0.3 mm.

Check the following:

1. Is there a timing belt between the spindle motor pulley and the spindle pulley ?

2. Does your virtual pendent on the computer screen show a cutter with a "green arrow" ?  . If it shows a red arrow  , the spindle will not rotate.

Continue to [trouble shooting, the engraving results are poor.](#)

Continue to [the table of contents.](#)

From:

<https://manualscyborg-engraverscom.webhosting.be/> - cyborg-engravers

Permanent link:

https://manualscyborg-engraverscom.webhosting.be/doku.php?id=en:x300:poor_engraving_results&rev=1664375442

Last update: 2022/09/28 16:30

