

Park spindle up



The PARK Z  +  function will move the spindle assembly to the absolute Z 0 position or all the way up.

Activating Park Z. Press the SHIFT key and then the Z-AXIS JOG UP ARROW to raise the spindle assembly to the absolute Z 0 position. Keypad status bar display: "Parking ..."

Return to [the keypad overview](#).
Continue to [the table of contents](#).

From:
<https://manualscyborg-engraverscom.webhosting.be/> - cyborg-engravers

Permanent link:
https://manualscyborg-engraverscom.webhosting.be/doku.php?id=en:x300:shift_raise_spindle_key&rev=1664100788

Last update: 2022/09/25 12:13

