

Move spindle down 1 mm



Press the SHIFT  key and then the Z-AXIS JOG DOWN ARROW  to lower the spindle exactly 1 mm.

This key combination can be used several times one after the other. Each time the spindle will lower mm.

Return to [the keypad overview](#).
Continue to [the table of contents](#).

From:
<https://manuals.cyborg-engravers.com/> - **cyborg-engravers**

Permanent link:
https://manuals.cyborg-engravers.com/doku.php?id=de:x300:shift_lower_spindle_key

Last update: **2023/06/16 09:42**

