



1.2 Component names and functions

Front view



1	spindle
2	cutter knob
3	graduated depth regulating nose
4	spring pressure ring
5	spindle motor
6	dust extraction hose
7	motor pulley
8	spindle pulley
9	dust extraction boot
10	nosecone for depth control

Rear view



1	Socket for power supply cable
2	On/Off switch (main switch)
3	Home setting of Y-axis motor
4	Ethernet socket
5	Socket for vacuum cleaner control
6	Nameplate X-200 with serial number

Virtual pendent



coordinates of the spindle position

jog speed scale

job speed information

start - pause - resume

status- and comments field

vacuum cleaner on/off
actual home position
uni- or bidirectional
rotary engraving
or diamond scratching

movement control keys

Continue to [the installation environment](#).
Continue to [the table of contents](#).

From:

<https://manuals.cyborg-engravers.com/> - **cyborg-engravers**

Permanent link:

<https://manuals.cyborg-engravers.com/doku.php?id=en:x200:components>

Last update: **2025/04/17 14:53**

