



1.2 Component names and functions

Front view



1	spindle
2	cutter knob
3	graduated depth regulating nose
4	spring pressure ring
5	spindle motor
6	dust extraction hose
7	motor pulley
8	spindle pulley
9	dust extraction boot
10	nosecone for depth control

Rear view



1	Socket for power supply cable
2	On/Off switch (main switch)
3	Home setting of Y-axis motor
4	Ethernet socket
5	Socket for vacuum cleaner control
6	Nameplate X-200 with serial number

Virtual pendent



Ga verder naar [de installatie omgeving](#).

Ga verder naar [de inhoudstafel](#).

From:

<https://manualscyborg-engraverscom.webhosting.be/> - **cyborg-engravers**

Permanent link:

<https://manualscyborg-engraverscom.webhosting.be/doku.php?id=en:x200:components&rev=1744894149>

Last update: **2025/04/17 14:49**

