

# Daily maintenance

---

Periodic maintenance is of utmost importance to keep your machine in optimal working condition and to give it a long lifecycle.

When performing periodic maintenance, try to follow the prescriptions which follow hereunder.

It may be a good idea to write down your maintenance activities in a table.

- Vacuum clean your table and all accessible areas with a vacuum cleaner. Never use compressed air to get rid of chips, dust and debris.
- Check the status of your cutters. Do not use dull or broken cutters. To check the status of your cutters use a good magnifying glass.

**Continue to [weekly maintenance](#).**

**Continue to [the table of contents](#).**

From:

<https://manualscyborg-engraverscom.webhosting.be/> - **cyborg-engravers**

Permanent link:

<https://manualscyborg-engraverscom.webhosting.be/doku.php?id=en:x200:daily&rev=1745475838>

Last update: **2025/04/24 08:23**

