

Move spindle down 1 mm



Press the SHIFT  key and then the Z-AXIS JOG DOWN ARROW  to lower the spindle exactly 1 mm.

This key combination can be used several times one after the other. Each time the spindle will lower 1 mm.

Return to [the keypad overview](#).
Continue to [the table of contents](#).

From:

<https://manuals.cyborg-engravers.com/> - **cyborg-engravers**

Permanent link:

https://manuals.cyborg-engravers.com/doku.php?id=en:x200:shift_lower_spindle_key

Last update: **2025/04/22 11:13**

