


Component names and functions

Front view



1	spindle
2	cutter knob
3	graduated depth regulating ring
4	spring pressure regulating ring
5	spindle motor
6	dust hose
7	motor pulley
8	spindle pulley
9	vacuum boot
10	depth limiting nosecone

Rear view

{afbeelding}

1	power supply socket
2	On/off switch (main switch)
3	socket for engraving motor control
4	socket for rotary device (optional)
5	socket for vacuum control (aux 1)
6	socket for mister control (aux 2)
7	socket for Z-axis proximity switch
8	socket for Y-axis motor

9	socket for Z-axis motor
10	ethernet socket

Virtual pendent

{afbeelding} ¹⁾

¹⁾

uitleg bij de afbeelding zit nu mee in de afbeelding verwerkt - moet afzonderlijk, zodat de tekst vertaalbaar is

From:
<https://manualscyborg-engraverscom.webhosting.be/> - **cyborg-engravers**

Permanent link:
<https://manualscyborg-engraverscom.webhosting.be/doku.php?id=en:x300:components&rev=1663417630>

Last update: **2022/09/17 14:27**

