

Go home

CKGE_TMP_i Go Home

The "Go Home" *hot key* functions as a return to 0,0 soft home and tool lift key. *Press the GO HOME hot key* .

Keypad status line display:

"Going Home ..."

From:

<https://manualscyborg-engraverscom.webhosting.be/> - **cyborg-engravers**

Permanent link:

https://manualscyborg-engraverscom.webhosting.be/doku.php?id=en:x300:go_home_key&rev=1664052856

Last update: **2022/09/24 22:54**

