

Cyborg X-300 Parts List

Part number	Description	Quantity
A31582	Spindle bearing	4
A31674	Spindle wave washer	3
https://manual.ketele.com/doku.php/intern/artikels/19327	Spindle shaft retaining ring (10 pcs)	1
A31660		
A31783		
A31345		
A31615		
A31614		
A31463		
S30696		
18804		
18875		
A31686		
19695		
A31233		
A31631		
A31161		
A31632		
A31160		
A31616		
A31346		
A31811		
A31069		
A31573		
A31447		
A31445		
A31445		
A31442		
A32653		
20174		
02447		
19228		
A31766		
18947		
18959		
A31464		
19891		
18928		
A31613		
A31676		

Last update:
2022/10/18
15:44

en:x300:parts_list https://manualscyborg-engraverscom.webhosting.be/doku.php?id=en:x300:parts_list&rev=1666100684



From:
<https://manualscyborg-engraverscom.webhosting.be/> - **cyborg-engravers**

Permanent link:
https://manualscyborg-engraverscom.webhosting.be/doku.php?id=en:x300:parts_list&rev=1666100684

Last update: **2022/10/18 15:44**

