

Thesaurus: terminology

Gantry	(uitleg)	(link machine components)
Spindle carriage	(uitleg)	(link machine components)
IEC type connector	(uitleg)	
ethernet cable	(uitleg)	
Line height	(uitleg)	
Base line	(uitleg)	
(Left and right) margins	(uitleg)	
Justification	(uitleg)	
Condensation	Condensation is when the width of the characters on a text line is reduced. This can be done automatically because otherwise, the text would not fit onto a single text line. When using a conventional word processor, when entering a text, it will automatically include a soft return at the end of each line as soon as the length of the text exceeds the available space between the margins. When text is entered on a text line in Symmetry, however, your cursor will not jump automatically to a next line. Symmetry will try to cram all text onto the current text line, by starting to <i>condense</i> the text as soon as the text line is full. You can also manually modify the condensation, for aesthetic purposes, to create a more balanced job layout, for example. When a job contains multiple text lines, changing the condensation for one text line might also change the condensation on other text lines, depending on the condensation mode which you have set in Symmetry for that specific job.	
Intercharacter space	(uitleg)	
Italicisation	(uitleg)	
Small caps font	A font where the lowercase characters have the same form as uppercase characters, but are smaller. Cipher fonts that are small caps are: Trophy Block and Futura 1L; TrueType small caps fonts are Bank Gothic and quite a few Copperplate fonts.	

From:
<https://manualscyborg-engraverscom.webhosting.be/> - **cyborg-engravers**

Permanent link:
<https://manualscyborg-engraverscom.webhosting.be/doku.php?id=en:x300:thesaurus&rev=1649944517>

Last update: **2022/04/14 15:55**

