


# The View menu

## Menu Options



The first three options are checkboxes. By selecting each one, you will activate or deactivate that function. The image to the right shows the **View** menu with the **Display Object Outlines** and **Show Pause Points** options checked.

- **Display Object Outlines:**
  - *Activating* will have a dashed line appear around text lines and images. This will make it easier for the operator to visualise and compare the positions of text lines and image boxes.
  - *Deactivating* will give you a clearer view of what the engraved end result will actually look like.
- **Pointer Ruler Guides**
  - *Activating* this will turn your mouse cursor into a crosshair.
  - *Deactivating* will have your cursor return to the standard arrow-shaped Windows cursor.
- **Show Pause Points**
  - *Activating* it will make the colour of your text alternate between black and red. Each colour change indicates a pause instruction. The machine will stop engraving, the spindle will return to its up position and stop rotating, allowing the operator to exchange cutters.
  - *Deactivating* it will show all texts in black.

The last option is not a checkbox. The > arrow on the right will show you the batches from which you can choose.

- **Show Batch**

From:  
<https://manualscyborg-engraverscom.webhosting.be/> - cyborg-engravers

Permanent link:  
[https://manualscyborg-engraverscom.webhosting.be/doku.php?id=nl:symmetry:menu\\_view&rev=1655384230](https://manualscyborg-engraverscom.webhosting.be/doku.php?id=nl:symmetry:menu_view&rev=1655384230)

Last update: 2022/06/16 14:57

