

Wekelijks onderhoud

Periodic maintenance is of utmost importance to keep your machine in optimal working condition and to give it a long lifecycle.

When performing periodic maintenance, try to follow the prescriptions which follow hereunder.

It may be a good idea to write down your maintenance activities in a table.

- Verify the brass cutter knobs around the cutters. They must have an undamaged clean thread. Only use cutter knobs supplied by your dealer, and specifically made for the Cyborg X-300.
- Verify that the machine is always standing on a stable table or support, with sufficient space around it.

Continue to [monthly maintenance](#).

Continue to [the table of contents](#).

From:

<https://manualscyborg-engraverscom.webhosting.be/> - cyborg-engravers

Permanent link:

<https://manualscyborg-engraverscom.webhosting.be/doku.php?id=nl:x300:weekly&rev=1670251342>

Last update: 2022/12/05 15:42

